

1/53




Fig. 1

2/53




Fig. 2A

3/53




Fig. 2B

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

4/53




Fig. 3

5/53




Fig. 4

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

6/53




Fig. 5

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

7/53






Fig. 6

8/53

Fig. 7



9/53




Fig. 8

10/53





Fig. 9

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

11/53



12/53





Fig. 11

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

13/53


Fig. 12



Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation


14/53

Fig. 13




15/53

Fig. 14




16/53

Fig. 15



17/53

Fig. 16



18/53




Fig. 17

19/53





Fig. 18

20/53


Fig. 19



Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

21/53

Fig. 20



22/53





Fig. 21

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation


23/53

Fig. 22



Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

24/53



Internal duct 320




Fig. 23

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001, Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

25/53





Fig. 24

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

26/53



Fig. 25



27/53





Fig. 26

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

28/53





Fig. 27



29/53




Fig. 28

30/53




Fig. 29

31/53





Fig. 30

32/53



33/53




Fig. 32

34/53




Fig. 33

35/53




Fig. 34

36/53

System Name	Pre-Repair Burial Status	Date of Fault	Seabed Type	Type of Fault	Water Depth	Type of Armour Repair Ship
CANUS 1	Surface Laid	1-Mar-98	Sand	Dredging	65 ft	Double Armor
TAT 7	Surface Laid	18-Apr-86	Sand	Anchor	90 ft	Mercury
TAT 7	Surface Laid	10-Aug-89	Sand	Fishing	175 ft	C.S. Alert
TAT 7	Unknown	9-Aug-93	Unknown	Repeater	160 ft	Global Mariner
TAT 8	Postlay Buried	10-Aug-93	Unknown	Unknown	90 ft	Global Marine
				LWP		

Fig. 35

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

37/53




Fig. 36

38/53




Fig. 37

39/53





Fig. 38

40/53

Fig. 39



Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

41/53




Fig. 40

09988821 061706

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

42/53




Fig. 41

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

43/53






Fig. 42

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal et al.; Tel: 202/371-2600
Title: Cable Installation


44/53

Fig. 43



45/53

Fig. 44



46/53




Fig. 45

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

47/53




Fig. 46

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

48/53




Fig. 47

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

49/53

Pipe Recovery Tool




Fig. 48

50/53




Fig. 49

09/988,821 D637063

Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

51/53





Fig. 50

52/53

Fig. 51





Fig. 52



Appl. No. 09/988,821; Filed: November 20, 2001
Dkt. No. 1757.0260001; Group Art Unit: 3662
Inventor(s): Vidal *et al.*; Tel: 202/371-2600
Title: Cable Installation

53/53





Fig. 53